

THE CAUSE OF THE LOADING DELAY WAS DUE TO A PROBLEM WITH THE CARGO PUMP AT MT. SNAPPER

*Antonio Herbert Mangiri¹, Welem Ada², Muhammad Rifani³,

¹ Diploma IV Program, Politeknik Pelayaran Makassar, Makassar, Indonesia

² Department of Nautical, Politeknik Ilmu Pelayaran, Makassar, Indonesia

*** Corresponding Author:**

Antonio Herbert Mangiri

Diploma IV Program, Politeknik Ilmu Pelayaran Makassar, Makassar, Indonesia

Jl. Tentara Pelajar No. 173 Makassar, 90172, Indonesia

Email: antonioherbertmangiri@gmail.com

Article Info: Received march 11, 2026. Revised march 13, 2026. Accepted april 09, 2026

ABSTRACT

In the operation of loading and unloading a cargo on a ship, special expertise and more attention are needed to support the smooth operation of the ship. In addition to operational problems, negligence in supervision of cargo can also result in hazards to ships, such as overflow and contamination of other cargoes, in this paper explains the preparations that occur in the implementation of loading and unloading operations and anticipating failures both from the ship and the dock. There are elements that can hinder the stages of loading operations when the ship is docked on the jetty, including the performance of the cargo pump, the initial circulation process, and the understanding of the guard officer himself. To overcome these things is by following every standard operating procedure that has been set, conducting good supervision during guard service, and routinely carrying out regular checks every hour so that safe, smooth, and proper cargo operations can be realized.

Keywords: *Loading and Unloading Operations, Tankers, Liquid Cargo*

ABSTRAK

Dalam operasi bongkar muat suatu muatan di atas kapal, dibutuhkan suatu keahlian khusus dan perhatian lebih guna menunjang kelancaran operasional kapal. Selain masalah operasional, kelalaian pengawasan terhadap muatan juga bisa mengakibatkan bahaya terhadap kapal, seperti overflow dan terkontaminasi muatan lain, dalam penulisan ini menjelaskan tentang persiapan yang terjadi dalam pelaksanaan operasi bongkar muat dan mengantisipasi kegagalan-kegagalan baik faktor dari pihak kapal maupun pihak dermaga. Terdapat unsur-unsur yang dapat menghambat tahapan operasi pemuatan saat kapal sedang sandar pada jetty, yang diantaranya yaitu kinerja pompa cargo, proses sirkulasi awal, pemahaman dari perwira jaga itu sendiri. Untuk mengatasi hal-hal tersebut adalah dengan cara mengikuti setiap standart operasional prosedur yang telah ditetapkan, melakukan pengawasan yang baik selama berdinis jaga, dan rutin menjalankan regulary check setiap jam sehingga operasional cargo yang aman, lancar, dan tepat dapat terwujud.

Kata kunci: Operasi Bongkar Muat, Kapal Tanker, Muatan Cair

This is an open access article under the CC BY 4.0 license.



Citation: Mangiri, A.H., Ada, W., Rifani, M . 2026. The Cause Of The Loading Delay Was Due To A Problem With The Cargo Pump At Mt. Snapper. *Jurnal Andromeda*, 10(1), 48-55. DOI: <https://dx.doi.org/10.48192/ard.v10i1.874>

1. INTRODUCTION

Ships are means of sea transportation that function to move goods or cargo from one location to another. The operation is carried out by the crew consisting of the Captain or Master as the leader, the Chief Engineer as the Head of the Engine Room (KKM), and the watch officers. Because conditions outside and inside the ship are often unpredictable accurately, the crew must always be vigilant, pay full attention, and be alert in taking action on any situation that arises. Although loading and unloading are two different activities, they have similarities in the aspects of occupational safety whose regulations are listed in the ISM Code (International Safety Management Code). Loading and unloading activities on tankers are one of the main operations besides navigation activities on shipping lanes. The smooth running of this process is influenced by various factors, including the condition of loading and unloading equipment, human resource competence, environmental conditions, and other supporting aspects. On tankers, *the cargo pump* is the main tool that ensures that the cargo transfer process runs smoothly, both during loading and unloading at the terminal and when transferring between ships. If there is a problem during the process, loading and unloading activities can be stopped or changed, so that ship operations are disrupted and costs can increase. Loading and unloading operations are hampered due to heavy density loads, then cargo pumps that are not yet in a condition ready to operate. The solution to the root of this problem is that the ship only needs to circulate on the line up that has been prepared, but the deck crew and guard officers on duty do not understand the operation too well to circulate, so the senior officer (*Chief Officer*) intervenes to take over the operation. On that basis of loading and unloading operations, we must also ensure the safety aspect in loading and unloading operations, by paying attention to the internal (ship) and external (jetty) aspects are ready before the implementation of loading and unloading is carried out, for this reason, the author

feels the need to further study this topic in a scientific paper entitled "The Causes of Cargo Operation Obstruction Due to Problem 2 at the Cargo Pump in MT. SNAP".

2. METHOD

This research was conducted at MT. KAKAP, which is one of the Oil Product Tanker ships owned by PT Pertamina International Shipping. as a Deck Cadet on the MT ship. SNAPPER from November 23, 2023 to December 06, 2024. In writing this scientific paper, the author uses the method of data collection through observation. This approach provides a deeper and more comprehensive understanding of the object being studied, so that the author can answer problems, collect relevant data, and draw conclusions according to conditions in the field. Through direct observation, the author can see and feel for himself various things that require special attention, including the obstacles that arise during the process of loading and unloading the ship, the factors that cause these obstacles, and the efforts made to overcome them.

The focus of the research includes the cause of the loading delay due to problems with the pump in accordance with the applicable rules. Data collection was carried out using observation methods, interview methods and documentation methods to obtain factual and accurate information about the loading process in MT. SNAPPER All data is analyzed using qualitative methods systematically to understand the problem, analyze the implementation of loading, and find optimal solutions in the implementation of loading in MT. SNAPPER

3. RESULTS AND DISCUSSION

3.1 A Brief History of MT. SNAPPE

Figure 1. MT. SNAPPER



MT Kakap is an oil tanker owned by PT *Pertamina Internasional Shipping* which was built at the PT. DOK & Shipping Surabaya in Indonesia in 2012. This ship, also known as Kakap/N.08602, has specifications as an oil tanker with a capacity of around 6,500 tons. The ship has a length of 108 meters and a draft depth of 9.30 meters, using a double hull design that was common at the time of its construction.

Gambar 2. Ship Particular

SHIP'S PARTICULARS																																	
NAME MT KAKAP CALL SIGN PTOK FLAG INDONESIA PORT OF REGISTRY JAKARTA OFFICIAL NUMBER 2012 Pst no.7592/L IMO/LOYDS NUMBER 9504401 CLASS SOCIETY BKI CLASS NOTATION SM, A100, Oil Tanker ESP P & I CLUB NORTH OF ENGLAND P&I ASSOCIATION LIMITED 109 The Quayside, Newcastle upon Tyne, NE15DU UK		KEEL LAID 19-Dec-08 LAUNCHED 19-Nov-10 DELIVERED 30-Aug-12 SHIPYARD PT DOCK DAN PERKAPALAN SURABAYA																															
		SATELLITE COMMUNICATION INM-F INM-C E-MAIL kakap@pertamina.com PHONE +628118723900 FAX TELEX MMSI 525003175 EX. NAMES N/A CS / FLAG INDONESIA																															
OWNERS PT. PERTAMINA INTERNATIONAL SHIPPING PATRA JASA OFFICE TOWER LANTAI 14, JL. GATOT SUBROTO, KAV. 32-34, KEL. KUNINGAN TIMUR, KEC. SETIA BUDI, KOTA ADMINISTRASI, JAKARTA SELATAN, 12950 TEL.+62213815111 FAX.+62214930441																																	
OPERATORS PT. PERTAMINA TRANS KONTINENTAL JL. KRAMAT RAYA NO 29, RT11 / RW 2 KRAMAT, KEC. SENEN, KOTA JAKARTA PUSAT, DAERAH KHUSUS IBUKOTA JAKARTA, 10450 TELP.+62151923005 FAX.+6215192006																																	
PRINCIPAL DIMENSIONS LOA 108.00 M LBP 102.00 M BREADTH (Extreme) 19.20 M DEPTH (moulded) 9.30 M HEIGHT (maximum) 34.60 M BRIDGE FRONT - BOW 80.90 M BRIDGE FRONT - STERN 27.10 M BRIDGE FRONT - MFOLD 30.30 M																																	
TONNAGE NET 1,765 T GROSS 5,570 T GROSS Reduced for SBT N/A		TANK CAPACITIES (cbm) CARGO TANKS (88 %) BLST TKS (100 %)																															
LOAD LINE INFORMATION TROPICAL 3.186 M SUMMER 3.311 M WINTER 3.436 M LIGHTSHIP 7.164 M NORMAL BALLAST COND 4.731 M DWT WITH SBT ONLY 4021.40 MT PWA 178 mm TPC @ Summer draft 17.78 T		<table border="1"> <thead> <tr> <th>GROUP I (1 & 4 P/B)</th> <th>GROUP II 2 & 5 P/S</th> <th>GROUP III 3 P/S</th> <th>TOTAL</th> </tr> </thead> <tbody> <tr> <td>3186,661</td> <td>3157,965</td> <td>1726,589</td> <td>8071,2</td> </tr> <tr> <td>SLOP P 127,083</td> <td>SLOP S 127,211</td> <td>F.W Tanks 100% 250,00</td> <td>TOTAL 504,294</td> </tr> <tr> <td>FPT C 263,20</td> <td>DEEP C 224,53</td> <td>4 P/S 568,14</td> <td>TOTAL 3671,450</td> </tr> <tr> <td>1 P/B 797,40</td> <td>2 P/S 547,72</td> <td>5 P/S 559,40</td> <td></td> </tr> <tr> <td></td> <td></td> <td>AFT 264,08</td> <td></td> </tr> </tbody> </table>		GROUP I (1 & 4 P/B)	GROUP II 2 & 5 P/S	GROUP III 3 P/S	TOTAL	3186,661	3157,965	1726,589	8071,2	SLOP P 127,083	SLOP S 127,211	F.W Tanks 100% 250,00	TOTAL 504,294	FPT C 263,20	DEEP C 224,53	4 P/S 568,14	TOTAL 3671,450	1 P/B 797,40	2 P/S 547,72	5 P/S 559,40				AFT 264,08							
GROUP I (1 & 4 P/B)	GROUP II 2 & 5 P/S	GROUP III 3 P/S	TOTAL																														
3186,661	3157,965	1726,589	8071,2																														
SLOP P 127,083	SLOP S 127,211	F.W Tanks 100% 250,00	TOTAL 504,294																														
FPT C 263,20	DEEP C 224,53	4 P/S 568,14	TOTAL 3671,450																														
1 P/B 797,40	2 P/S 547,72	5 P/S 559,40																															
		AFT 264,08																															
MACHINERY / PROPELLER / RUDDER MAIN ENGINE WARTSILA 6L 32 R/P 3580 KW 2760 RPM 750 M.C.R RPM 750 X KW 2760 N.C.R RPM 715 X KW 2346 EMER D.G. (1) Cummins INC 6BTS.9-D(M) PROPELLER WARTSILA NETHERLAND B.V., KEYLESS FIXED PITCH PROPELLER, STEEL, 1 SET GENERATOR (3 sets) YANMAR 6NY 16L - NSX 360 KW RUDDER SPEERY GYRO 2 POWER UNIT SINGLE RUDDER WITH 2 RAMS & 2 CYLINDERS STEERING GEAR DESIGN ELECTRO-HYDRULIC, WITH HELM PUMP AS EMERGENCY POWER DRIVE N/A P/W GENERATOR CAP N/A		BUNKER TANKS B35 TANK (100 %) M³ MDO TK (P) 196,868 MDO TK (S) 195,831 HSD TK (P) 39,877 HSD TK (S) 39,826 FO DRAIN TK 12,840 MDO SETTLING TK 20,806 HSD SETTLING TK 20,275 MDO DAY FOR AE TK 2,790 HSD DAY FO AE TK 2,830 MDO DAY TK 1 13,225 MDO DAY TK 2 13,746 TOTAL 558,114																															
CARGO AND BALLAST PUMPING SYSTEM <table border="1"> <thead> <tr> <th>MAIN PUMPS</th> <th>NO.</th> <th>CAPACITY</th> <th>HEAD</th> <th>RPM</th> </tr> </thead> <tbody> <tr> <td>CARGO OIL P/P%</td> <td>3</td> <td>300 m³/H</td> <td>N/A</td> <td>3570</td> </tr> <tr> <td>CARGO EDUCTOR</td> <td>-</td> <td>N/A</td> <td>N/A</td> <td>N/A</td> </tr> <tr> <td>STRIPPING PUMP</td> <td>2</td> <td>50 m³/H</td> <td>N/A</td> <td>1770</td> </tr> <tr> <td>BALLAST PUMP</td> <td>2</td> <td>150 m³/H</td> <td>25 M</td> <td>1750</td> </tr> <tr> <td>TK CLEANING P</td> <td>1</td> <td>70 m³/H</td> <td>N/A</td> <td>3555</td> </tr> </tbody> </table>		MAIN PUMPS	NO.	CAPACITY	HEAD	RPM	CARGO OIL P/P%	3	300 m ³ /H	N/A	3570	CARGO EDUCTOR	-	N/A	N/A	N/A	STRIPPING PUMP	2	50 m ³ /H	N/A	1770	BALLAST PUMP	2	150 m ³ /H	25 M	1750	TK CLEANING P	1	70 m ³ /H	N/A	3555	WINDCHES / WINDLASS / ROPES / EMERGENCY TOWING WINDCHES N/A 1 Hydraulic Mooring Winch MRG WRES N/A N/A Winch BHC N/A 1 P/S Brake Cap : 28.20 T WINDLASS 2 N/A Hydraulic Mooring Windlass RW05-012 DM.10-60 FIRE WIRE 1 1 16 mm, Length 35 M, Galvanized, ANCHOR 2 N/A Anchor 3380 kg, Chain : Port 9 / Stbd 9 Sckls EMG. TOWING N/A N/A	
MAIN PUMPS	NO.	CAPACITY	HEAD	RPM																													
CARGO OIL P/P%	3	300 m ³ /H	N/A	3570																													
CARGO EDUCTOR	-	N/A	N/A	N/A																													
STRIPPING PUMP	2	50 m ³ /H	N/A	1770																													
BALLAST PUMP	2	150 m ³ /H	25 M	1750																													
TK CLEANING P	1	70 m ³ /H	N/A	3555																													
CARGO HOSE CRANES 1 Set x 5 Ton		LIFE BOATS 5,00m x 2,20m x 1,20 m 2x 26 person Totally enclosed life boat LIFE RAFTS 2 x 30 persn PROV. CRANE CR.10-65/CR10-001 SPARE PART CRANE CR.10-64/CR15-001																															
IG / VAPOR EMISSION / VENTING IG BLOWER CAPACITY (3 nos) N/A P/V VALVE PR./VAC. SETTING 1400 mm/wg. -350 mm/wg P/V BREAKER PR./VAC. SETTING N/A		MANIFOLD ARRANGEMENT (400 mm / Steel) Distance of cargo manifold to cargo manifold 1500 mm Distance of bunker manifold to cargo manifold 1300 mm Distance of manifolds to ship's rail 3900 mm Distance of spill tray grating to centre of manifold 1200 mm Distance of main deck to centre of manifold 1600 mm Distance of top of rail to top of manifold 1270 mm Distance of top of rail to centre of manifold 3800 mm Distance of manifold to ship side 4100 mm Distance of manifold from keel 10.90 M																															
Draft Normal ballast : (P)3.25 m,(N) 5.00 m Summer Draft : FIB (0m)-AII (6.00m) Propeller Immr. : 113.6 %		FIRE FIGHTING SYSTEM E/RM CO 2 PUMP ROOM CO2 CARGO/DK AREA FOAM AND WATER																															

The Cause of the Loading Delay Was Due to a Problem with the Cargo Pump at Mt. Snapper ... (Mangiri)

MT. KAKAP is an Oil Tanker owned by *Pertamina International Shipping* which is under the Indonesian flag. As for Ship Particular from MT. KAKAP as the place where the author practiced for 12 months and 13 days. MT. KAKAP is an *Oil Tanker* cargo ship operated by *Pertamina International Shipping* to serve the needs of *Lubricant Base Oil* as a *MOTHER SHIP* operating in Jakarta.

Based on the data above which contains *the particular ship* of the ship, this information can be used as an internal factor in analyzing various problems that may occur. In addition, the data can also be used as a reference to assess the extent of the effectiveness of ships in carrying out shipping activities.

3.2 Research Results

Based on research conducted by the author while conducting sea practice (PRALA) on loading activities on MT ships. It was found that operational obstacles were mainly caused by suboptimal conditions of the cargo pump due to inconsistent implementation of checking and maintenance procedures before operations began. Field data shows that some crews have not fully implemented the Standard Operating Procedure (SOP), especially at the pre-loading inspection stage which includes checking pump working pressure, leakage, lubrication, and the readiness of other support systems.

Cargo pump maintenance that is not carried out regularly causes several technical problems, such as fluctuations in discharge pressure, overheating of pump components, and decreased pumping capacity. This condition triggers delays in the loading and unloading process, so that the duration of the ship's port stay is longer than the standards set by the company.

Observations during loading activities show several frequent disturbances, such as:

1. A drop in pump pressure (pressure drop) which results in an unstable pumping rate.
2. Increased temperature of pump components, especially in the bearing, which has the potential to cause overheating.
3. Excessive vibration due to lack of lubrication or misalignment of pump components.
4. Load times are longer than standard, reaching 10–20% slower than the set target.

The technical glitch had a direct impact on the loading and unloading process, causing delays that impacted the ship's overall operations. From a business perspective, port stay delays affect the ship's operational costs and the charterer's level of confidence.

In addition to technical factors, this study also found that the human resource aspect is also the main cause. The crew's understanding of SOPs, especially new crews or those with limited experience, is inadequate. This can be seen from the lack of thoroughness in carrying out the pre-operation checklist and the lack of initiative to report the initial symptoms of pump failure.

3.3 Discussion

The results of the study show that the problem with loading activities in MT. Snapper is actually a combination of procedural inconsistencies and weaknesses in the maintenance aspect of the equipment. In tanker operations, the cargo pump is the center of the loading and unloading process, so the reliability of the pump greatly determines the operational efficiency of the ship.

1. The Gap between SOPs and Field Implementation

The company's SOP clearly stipulates that each cargo pump must undergo a detailed inspection before use, including checking for lubrication, leakage, pipe connections, valve condition, and control panel readiness.

2. Impact of Less Optimal Maintenance on Pump Performance

Cargo pump maintenance that is not carried out regularly causes a domino effect on the load transfer system. Unstable pump pressure results in a longer pumping process, while rising temperatures can accelerate the deterioration of internal components. Excessive vibration also indicates the potential for more serious damage if not treated immediately.

3. The Role of Crew Competence and Officer Supervision

The quality of maintenance and checking implementation is highly dependent on the competence and discipline of the crew. The findings of the study show that not all crews technically understand the functions and working mechanisms of cargo pumps, so the initial symptoms of malfunction are often

not recognized. The lack of periodic training is also a factor causing the decline in the quality of work.

4. Implications for Ship Operational Efficiency

Delays in the loading process caused by problems at the cargo pump directly reduce the operational efficiency of the ship. Longer docking times result in increased energy consumption, the use of various supporting equipment, and increased costs that ships must bear while in port.

5. Imperfect work planning (Design Faults).

In the implementation of loading, the success of the operation is highly dependent on the quality of the work planning carried out before the activity begins. Planning that is not comprehensively prepared can cause various obstacles during the process of moving loads, ranging from unpreparedness of equipment to miscommunication between parts.

The consequences of the inhibition of Cargo Operation are;

- a. Delay in Unloading/Loading Schedule
- b. Increased Operational Costs
- c. Decreased Ship Work Efficiency
- d. Disruption to the Next Cruise Schedule
- e. Potential Penalties or Sanctions

As for efforts to overcome obstacles that hinder cargo operations, to overcome obstacles that hinder cargo operations on MT ships. SNAPPER, there are several steps that can be taken, depending on the type and nature of the obstacle. Here are some common approaches that can be applied according to MT's *Chief Officer*. SNAPPER which refers to *Section IV* of the *IMO Manual on Oil Pollution*

- a. Evaluation and identification of issues
- b. Infrastructure and equipment upgrades
- c. Training and development
- d. Improved procedures and processes
- e. Coordination and communication
- f. Regulatory and compliance handling
- g. Regular maintenance

4. CONCLUSION

Based on the results of the study, it can be concluded that the obstacles to loading activities on MT ships. The snapper is caused by the lack of optimal implementation of the procedure for checking and maintaining the cargo pump before the operation begins. Cargo pumps that are not properly maintained cause technical problems and delays in the loading and unloading process. The lack of implementation of standard procedures by the ship's crew has an impact on the overall efficiency and operational effectiveness of the ship.

To overcome these obstacles, the Captain held Safety Meeting activities and periodically to all before and carrying out loading and unloading on the ship. Chief Officer Held familiarization on the form of evaluation related to what technicalities are needed according to the SOP cargo operation for smooth operation to occur, especially when the initial circulation begins the loading and unloading operation.

5. REFERENCES

- Agus Weda Bayuntara (2021). Efforts To Implement Loading And Unloading Procedures On Ships With Fishbone Analysis.
- Alkonusa, & Behrens, A. (2016). Definition Of Centrifugal Pump And Its Working Principle. *Alkonusa News*, 10.
- Analysis Of The Factors Causing Delays In Loading And Unloading Coils At PT. Daisy Pearl Ocean. *LOGISTICS*, 15(02).
- Badudu (2001:200). Knowledge Of The Loading And Unloading Process On Ship Will Be Accessed On March 07, 2024.
- Capt. Suyono, M.Mar, 2007, *Quantitative, Qualitative, And R&D Research Methods* Jakarta.
- Capt. Suyono, M.Mar, 2007, *Shipping Intermodal Transportation Export*
- Darmana, E., & Supriyadi, A. (2021). Analysis Of The Inhibition Of The Discharge Process At The Cargo Pump. *Marine Science And Technology Journal*, 1(2).
- Esterberg, K. G. In Sugiyono. (2020). *Quantitative, Qualitative, And R&D Research Methods*.
- Fauziah, F., Friska, U., Umardhi, F., Umardhi, F. F., Ibrahim, H., & Authors, Gianto. 1999. *Sea Port Operation*. Bandung Istopo. 2010. *Ships And Their Loads*. Jakarta *Import By Sea Edition IV*, Jakarta.
- K. (2024). International Operations Management. *Journal Of Management Science Publications (JUPIMAN)*, 3(1).
- KNKT (National Committee For Transportation Safety) Data From 2008.
- Mariani. (2022). Operational Management In The Company's Production Process. *Journal Of Economics And Management*, 2(1).
- Martopo Arso And Soegiyanto. 2004, *Handling And Regulation Of Loads*. Jakarta.
- Moleong, L. J. (2013). *Qualitative Research Methodology*. Bandung: Remaja Rosdakarya.
- Nasution, S., In Sugiyono. (2020). *TEXT Observation Report For Junior High School Class VII*. Bandung: Guepedi.
- National Transportation Safety Committee (KNKT).
- Sakinah. (2019). Loose Cargo Transportation Agreement In Loading And Unloading Ship Companies. *Ayan*, 8(5).
- Suryabrata, S. (2010). *Research Methodology*. Jakarta: Rajawali Pers Verawati, K., Prasetyo, A., Dunan Hamidi, H., & Karim Ladesi, V. (2022).